VeriClean SEALS™
Your higher standard for clean seals

TECHNICAL WHITEPAPER
V4 · 2026

MEDICAL DEVICES · QUALITY & VALIDATION ENGINEERS

Elastomeric seal surface cleanliness and ISO 13485 supplier qualification: closing the component-level documentation gap.

THE SPECIFICATION GAP · CCD · STANDARDS MAPPING

No current standard requires measuring or documenting the particle burden on seal surfaces at the component level. As-received commercial seals carry 1,000–98,500 particles/cm² at ≥1.3 µm — none detectable by visual inspection, and none present in any document your quality system currently holds.

PACIFICRUBBER.COM / VERICLEAN

PRP
Precision. Seals. Delivered.

Elastomeric seal surface cleanliness and ISO 13485 supplier qualification have a structural documentation gap: no current standard requires measuring or documenting the particle burden on seal surfaces at the component level. As-received commercial elastomeric seals have been measured across a SKU-average range of 1,000 to 98,500 particles per square centimeter (≥1.3 µm), with individual seals ranging from 630 to more than 127,000 particles per square centimeter (PRP measurement data) — none of those particles detectable by visual inspection, and none present in any document your quality system currently holds.

The VeriClean Cleanliness Qualification (VCQ) is the first analytical qualification service that closes this gap at the supplier qualification record level. It produces a quantitative characterization of seal surface contamination — as-received burden, processed burden following VeriClean Seals™ processing, and position relative to the PRP supply chain dataset — in a format directly applicable to the Device History Record.

The Specification Gap

Your contamination control program has owners, procedures, and records for every variable within its scope. Cleanroom classification, component cleaning validation, incoming inspection, extractables characterization, supplier qualification — each documented. What is absent from every one of those records is a quantitative characterization of the particle burden on the elastomeric seal surface at the time of installation. Not because it was evaluated and deemed acceptable. Because no measurement was ever taken and no standard required one.

THE STANDARD WAS DESIGNED FOR A DIFFERENT PROBLEM

ISO 3601-3 specifies surface inspection at ×2 magnification. This standard was designed to detect molding defects — flash, tears, surface damage. It does that job. It is not designed to address fluid-path contamination. At ×2 magnification, particles at ≥1.3 µm — the size range relevant to your application — are structurally invisible. The contaminants of primary concern in fluid system integrity begin below 25 µm and extend down to 1 µm. The gap between what ISO 3601-3 detects and what a calibrated particle counter measures at ≥1.3 µm sensitivity is not a flaw in the standard. It is the space in which this problem exists.

YOUR SUPPLIER IS COMPLIANT. THAT IS THE PROBLEM.

Your seal supplier ships seals that meet every published requirement. The certificate of conformance is accurate. The visual inspection passed. There is no negligence and no supply chain failure in the conventional sense. The seals are in spec. The spec does not address what enters your fluid system. This is not fixable by finding a better supplier — every supplier operates to the same inadequate standard.

> *"Your seal supplier will ship seals in spec. The spec is the problem."*

THE CONTAMINATION REQUIRES A METHODOLOGY THAT DOESN'T EXIST

Particles at ≥1.3 µm require extraction, counting, and documentation to detect. That methodology does not exist at the component level anywhere in the industry. This is the Specification Gap: not a supplier failure, not a process deviation, but a structural absence of a standard that was never written because the measurement infrastructure to support it was previously unavailable.

The contamination that ships on seal surfaces originates across multiple source classes through the manufacturing and supply chain sequence. A partial inventory: talc (1–20 µm) used as compounding filler and mold dusting agent; carbon black agglomerates (0.01–100 µm) as compounding ingredients liberated by surface shear; skin squames (20–50 µm) from operator handling in non-controlled environments; textile fibers (50–2,000+ µm) shed from non-PPE garments during handling and packaging. These represent four of eleven contamination classes documented in full — see the full technical paper for the complete taxonomy.

The measured consequence: as-received seals across standard commercial supply channels carry a SKU-average particle burden of 1,000 to 98,500 particles per square centimeter (≥1.3 µm), with individual seals from 630 to more than 127,000 particles per square centimeter (PRP measurement data). Within a single purchased bag, individual seal burden varies by more than 20-fold. None of these particles appear on any document associated with the part.



FKM (Viton) seal surface — as-received (left) vs. VeriClean processed (right). At ×2.5, surface contamination is subtle — this seal would pass standard incoming inspection. At ×20, particulate scatter and fiber contamination are measurable and documentable. VeriClean processing removes what inspection cannot detect. Scale bar: 250 µm.

Cyclic Contamination Displacement ™ — the delivery mechanism

The question for a quality system is not only what is on the seal surface at incoming. It is how that contamination reaches the fluid path in service. The mechanism is Cyclic Contamination Displacement™ (CCD): the progressive mobilization of surface-bound particulate into the process fluid, driven by normal

pressure cycling, thermal cycling, and mechanical displacement that every seal undergoes in service. CCD is not a malfunction. It is a consequence of the seal's designed function.

A seal's static wetted footprint — the compression contact zone visible in the gland geometry — is a small fraction of its total surface area. This is by design: gland geometry, compression, and material compliance are engineered for sealing performance. Under pressurization, thermal cycling, and mechanical cycling, the effective wetted area expands 3:1 to 8:1 beyond the static footprint (PRP measurement data). The seal is functioning as designed.

That expansion brings previously dry gland surface — and its contamination load — into contact with the fluid. Contamination release is cumulative and ongoing, not a one-time commissioning event. For a drug delivery pump completing thousands of actuation cycles across its implanted service life, this represents thousands of contamination delivery events drawing from a reservoir that was never characterized and is not reflected in any document in the device's history record.

CCD has a direct implication for sterility assurance. The sterilization bioburden model is built on the static wetted-area estimate from the gland geometry. That estimate understates the seal surface that CCD will bring into fluid contact during service — potentially by the same 3:1 to 8:1 factor. A surface not in fluid contact during sterilization exposure may carry residual bioburden into the fluid path across the device's service life. A seal sterilized as a loose component before assembly presents no such gap — the entire surface is accessible to the sterilization process, and CCD expands from a fully treated baseline.

Two structural limitations prevent downstream filtration from compensating for this source. First, at least one seal exists downstream of the last filtration stage in any real fluid system — at pump outlets, valve seats, or connection points. Contamination from those seals bypasses filtration entirely. Second, CCD-released contamination is not freely mobile in the fluid at the time of commissioning or initial sterilization. It enters the fluid progressively over operating cycles, after any filtration that was effective at initialization. The filter cannot intercept contamination that has not yet been released from the seal surface.

> For full CCD mechanism visualization — including wetted area expansion diagrams, operating cycle analysis, and the complete contamination class dataset — download the full technical paper: *'Surface Particulate Contamination on Elastomeric Seals'* at pacificrubber.com/resources.

Particle load variability and the limits of incoming controls

The contamination problem cannot be managed by visual inspection, lot-level assumptions, or supplier assertion — not because those methods are poorly executed, but because the variable is outside the detection range of every conventional incoming control.

Visual inspection in a standard receiving environment resolves particles above approximately 100 µm under favorable lighting. The particle population of primary concern for fluid system contamination in medical device applications begins below 25 µm and extends to 1 µm. The inspector who completes the incoming record and approves the lot for use has not seen the contamination on the surface. They cannot. Visual inspection is operating correctly within its designed capability. That capability simply does not cover this size range.

The Certificate of Conformance documents what was controlled: dimensional conformance, material lot, hardness, compression set, and the results of specified tests. No current industry standard requires surface

particle counts on an elastomeric seal CoC. Auditing the CoC more carefully will not reveal a number that was never generated.

Sampling-based incoming inspection compounds the limitation. Seal-to-seal variability within a single purchased lot reaches 20-fold in particle burden, measured under identical conditions, same lot number, same CoC. A statistically sound sample from that population cannot reliably characterize the worst individual seal in the box — and in a sterile fluid path, one high-burden seal installed at a critical fluid interface carries the consequence.

There is also a weak correlation between price, visual grade, and contamination burden — R=0.47 across the PRP database. A premium-priced seal is not a cleaner seal. The supplier selection process that produces the specification record does not produce a contamination control record, because no such record exists in the supply chain.

This variability requires a documented, repeatable measurement methodology applied at the SKU level — not lot level, not visual inspection, not supplier assertion. No current industry standard provides this methodology at component level. That infrastructure now exists.

Standards mapping — ISO 13485 requirement, current gap, and VCQ solution

The standards landscape for medical device elastomeric seals collectively covers dimensional tolerance, material chemistry, hardness, compression set, extractables and leachables, biological reactivity, and microbiological performance. What no standard in this framework addresses is the concentration of insoluble particles residing on the seal component surface at the time of installation — the input, not the output.

ISO 13485:2016 requires that your quality management system address contamination control as a design requirement, with documented procedures under Section 7.5 for any product with a cleanliness specification. The requirement is present. The gap is that no standard defines what characterization of seal surfaces is required to satisfy it — and the measurement infrastructure to produce that characterization has, until now, been unavailable. The VCQ engagement produces a documented, quantitative characterization of seal surface contamination in a format that directly fulfills this requirement for this specific component type.

FDA 21 CFR Part 820.70 requires process validation and environmental controls, and applies to processes where results cannot be fully verified by subsequent inspection. An incoming seal surface that carries an uncharacterized contamination and bioburden load, deployed in a sterile fluid path, satisfies both conditions for process validation applicability. The VCQ generates the process record that establishes a characterized and documented input baseline.

USP <788> governs particulate matter in finished injectable products — a system-level output test, not a component-level input characterization. A passing result at the system level does not tell you what the seal surface contributed across the cycles that preceded the measurement, or what it will contribute across the cycles that follow. USP <381> and <382> address chemical migration and extractables from elastomeric closures. Surface-deposited insoluble particles are not within their scope.

The gap does not appear as a nonconformance because it doesn't violate any existing requirement. No audit finding will cite the DHR for omitting data that no guidance document specifies. The gap shows up when the

failure mode it represents becomes visible — and by then, the absence of documentation makes root cause analysis substantially more difficult.

Seal contamination control documentation, 21 CFR 820 compliance, and component-level particulate characterization are currently unaddressed by any standard in this framework. The VCQ closes both at the supplier qualification record level.

What this means for Quality / Validation Engineers

For a Quality or Validation Engineer at an implantable OEM or diagnostics manufacturer, the Specification Gap has a direct consequence in the Device History Record. Every contamination variable is documented — except the particle burden on the elastomeric seal surface at installation. That variable has no entry in the DHR because no methodology existed to generate one. The audit answer today is "not characterized at this level." The VCQ changes that answer. A VCQ engagement produces a quantitative characterization of incoming seal surface contamination — as-received burden, processed burden, and supply chain position — in a format that is directly applicable to the DHR, defensible in an audit, and citable in a regulatory submission. The seal supplier qualification record gains a component it has never contained: a documented, reproducible characterization of the surface cleanliness of the specific lot installed in the device.

What's inside the full technical paper

The full paper — *'Surface Particulate Contamination on Elastomeric Seals'* — contains the complete mechanism, dataset, and methodology behind every claim in this document. Contents include:

- 11 contamination source classes — full taxonomy with morphology, size ranges (0.01 µm to 2,000+ µm), supply chain origin, and fluid-path impact
- Complete particle count dataset: 1,000 to 98,500 particles/cm² SKU-average; individual seals 630 to more than 127,000 particles/cm² (≥1.3 µm)
- Particle volume density analysis across 16 size buckets: 45,000 µm³/cm² to more than 5.4 million µm³/cm² SKU-average
- Within-lot variability: 3× lot-to-lot; 20× seal-to-seal within same bag
- Full CCD mechanism with wetted area expansion ratios (3:1 to 8:1) and operating cycle analysis
- Standards landscape mapping for medical devices: ISO 3601-3, USP <381>/<382>, USP <788>, ISO 13485, 21 CFR Part 820, EU MDR 2017/745 — scope and surface particulate coverage for each
- VeriClean Seals™ processing methodology and performance data
- 20 pages · 5,300 words · 24 cited references



VeriClean Qualification (VCQ) — Contamination Risk Bullseye, one of several visual analytical outputs in the VCQ report.

About the bullseye. The Contamination Risk Bullseye shown here is one of several visual analytical outputs in the VCQ report. Each marker represents independent particle extraction and quantification for an individual seal: n=15 as-received measurements and n=15 VeriClean-processed. The distribution of as-received markers across the chart reflects the seal-to-seal variability within a single submitted lot, and positions that population against the same compound family average from PRP's full supply chain dataset. The complete VCQ report delivers this and other visualizations alongside all raw particle count and volume data across 16 size bins.

The full data is available. The full paper is accessible now.

'Surface Particulate Contamination on Elastomeric Seals' — 20 pages · 5,300 words · 24 cited references. The complete mechanism, the complete dataset, and the measurement methodology that closes the Specification Gap.

Download at pacificrubber.com/resources

VeriClean Seals™ processing reduces surface bioburden by 92–100% as characterized under ISO 11737-1. This is a process characterization finding, not a batch-monitored VCQ deliverable. Results vary by elastomer compound and initial contamination state.

VeriClean Seals™ and Cyclic Contamination Displacement™ are trademarks of Pacific Rubber & Packing, Inc.